


PreciseFlex™ c10 4-Axis Robot

Energy Efficiency while Maximizing Workspace



most reliable, most energy-efficient


Wide Range of Applications



Lowest Power Consumption



Highest Workspace Density



1. Highest Workspace Density

2. Highest Reliability

3. Range of Motion

Z-Axis: 00, 1000, 1 1 0
()

4. Highest Throughput



